

**STANDARD DEPARTURE  
CHART INSTRUMENT  
(SID) - ICAO**

TA: 7000'  
VAR: 11W

TWR - 118.200

**PRAIA AIRPORT  
GVNP  
RWY03**



**AGTIL1E :** Climb on runway heading until passing 2500ft and 8DME/SNT. Turn right to join arc 10DME/SNT. Cross RDL130SNT at 6000ft or above. After crossing radial RDL180SNT follow track 270MAG to join RDL230SNT direct AGTIL.

**AGTIL1M :** Climb on runway heading until 3DME/SNT. Turn right to join arc 5DME/SNT. After crossing radial RDL160SNT follow track 255MAG to join RDL230SNT direct AGTIL.

**BULVO1E :** Climb on runway heading until passing 2500ft and 8DME/SNT. Turn right to join arc 10DME/SNT. Cross RDL130SNT at 6000ft or above. After crossing radial RDL180SNT follow track 270MAG to join RDL239SNT direct BULVO.

**BULVO1M :** Climb on runway heading until 3DME/SNT. Turn right to join arc 5DME/SNT. After crossing radial RDL160SNT follow track 255MAG to join RDL239SNT direct BULVO.

**BVT1E :** After departure turn right to join RDL037SNT direct BVT.

**CVS1E :** Climb on runway heading to join RDL027SNT direct CVS.

**NCL1E :** Climb on runway heading until passing 2500ft and 10DME/SNT. Turn left track 325MAG to join RDL346SNT direct NCL.

**SONVA1E :** Climb on runway heading until 5DME/SNT. Turn right track 120MAG to join RDL105SNT direct SONVA.

**SVT1E :** Climb on runway heading until passing 2500ft and 10DME/SNT then turn left track 315MAG to join RDL333SNT direct SVT. Cross 15DME/SNT above 4500ft.

**VONTO1E :** Climb on runway heading until 5DME/SNT. Turn right track 135MAG to join RDL121SNT direct VONTO.