

STANDARD DEPARTURE

AMILCAR CABRAL

RABIL AIRPORT

(SID)-ICAO

AIRPORT GVAC

GVAC

DESCRIPTION

RWY 01

RWY03

GVAC RWY 01

**BULVO1A** : Climb on runway track till 8 DME/CVS. Turn left to BULVO (RDL219CVS). Remain beyond 10 DME CVS.

**BULVO1K** : Climb on runway track till passing 2000ft. Turn left to BULVO (RDL219CVS).

**BVT1A** : Climb on runway track till passing 2500ft and 6 DME/CVS. Turn right direct BVT NDB. Remain beyond 8 DME/CVS.

**KESIK1A** : Climb on runway track till passing 2000ft. Turn left to KESIK (RDL317CVS) .

**NCL1A** : Climb on runway track till passing 2000ft. Turn left to intercept and follow RDL272CVS to NCL NDB. MSA 6500ft.

**PISPU1A** : Climb on runway track till passing 2500ft and 6 DME/CVS. Turn right to PISPU (RDL040CVS).

**PINPO1A** : Climb on runway track till passing 2500ft and 6 DME/CVS. Turn right to PINPO (RDL057CVS).

**POLMO1A** : Climb on runway track till passing 2500ft and 6 DME/CVS. Turn right to POLMO (RDL120CVS).

**RAMOL1A** : Climb on runway track till passing 2500ft and 6 DME/CVS. Turn right to RAMOL (RDL137CVS). Remain beyond 8 DME CVS.

**SNT1A** : Climb on runway track till 8 DME/CVS. Turn left to intercept and follow RDL206CVS to SNT VOR. Remain beyond 10 DME CVS.

**SNT1K** : Climb on runway track till passing 2000ft. Turn left to intercept and follow RDL206CVS to SNT VOR. Remain beyond 3 DME CVS.

**SVT1A** : Climb on runway track till passing 2000ft. Turn left to intercept and follow RDL283CVS to SVT NDB. MSA 4600ft.

GVAC RWY 19

**BULVO1B** : After departure follow R191CVS till 4 DME CVS. Turn right to follow RDL219CVS to BULVO.

**KESIK1B** : After departure follow R191CVS till 6 DME CVS. Turn right to KESIK (RDL317CVS).. Remain beyond 8 DME/CVS.

**NCL1B** : After departure follow R191CVS till passing 2000ft or 4 DME CVS. Turn right to intercept and follow RDL272CVS to NCL NDB.

**PISPU1B** : After departure follow R191CVS till 5 DME CVS. Turn left to intercept and follow arc 7 DME CVS. Crossing R137 follow track 029MAG to intercept and follow RDL040CVS to PISPU.

**PINPO1B** : After departure follow R191CVS till 5 DME CVS. Turn left to intercept and follow arc 7 DME CVS. Crossing R137 follow track 044MAG to intercept and follow RDL057CVS to PINPO.

**POLMO1B** : After departure follow R191CVS till 5 DME CVS. Turn left to intercept and follow arc 7 DME CVS. Crossing R169 follow track 099MAG to intercept and follow RDL120CVS to POLMO

**RAMOL1B** : After departure follow R191CVS till 5 DME CVS. Turn left to intercept and follow arc 7 DME CVS. Crossing R169 follow track 099MAG to intercept and follow RDL137CVS to RAMOL.

**SNT1B** : After departure follow R191CVS till 4DME CVS. Turn right to follow RDL206CVS to SNT VOR.

**SVT1B** : After departure follow R191CVS till passing 2000ft or 4 DME CVS. Turn right to intercept and follow RDL283CVS to SVT NDB.

GVBA RWY 03

**NCL1C** : Climb on runway heading till passing 1500ft. Turn left to follow track 284MAG to join QDR299BVT to NCL NDB. MSA over NCL6500ft.

**PISPU1C** : After departure join QDR029BVT to PISPU (RDL040CVS/80DME).

**PINPO1C** : After departure join QDR041BVT to PINPO (RDL057CVS/80DME).

**SNT1C** : Climb on runway heading till passing 1500ft. Turn left direct SNT VOR (RDL036SNT).

**SVT1C** : Climb on runway heading till passing 1500ft. Turn left to follow track 276MAG to join QDR289BVT to SISAU (N162116W0242011/QDR200NCL) then direct SVT NDB on QDR135SVT. MSA 4600ft.

GVBA RWY 21

**NCL1D** : After departure turn right to join QDR299BVT to NCL NDB. MSA over NCL is 6500ft.

**PISPU1D** : Climb on runway heading till passing 1500ft. Turn right to follow track 044MAG to join QDR029BVT to PISPU(RDL040CVS/80DME).

**PINPO1D** : Climb on runway heading till passing 1500ft. Turn right to follow track 049MAG to join QDR041BVT to PINPO (RDL057CVS/80DME).

**SNT1D** : After departure follow QDR216BVT to SNT VOR (RDL037SNT).

**SVT1D** : After departure turn right to join QDR289BVT to SISAU (N162116 W0242011 / QDR200NCL) then direct SVT NDB on QDR135SVT. MSA 4600ft.